



Assembly examples



Mounting examples of straight sensors in tanks or pipes with screw or weld-in attaching devices



Suggestions for a standard sensor mounting

The sensor sensitive part (tip) has to be put as nearer as possible to the area to be measured. It is important to ensure a good thermic contact between the sensor and the mean where measurement has to be made. Follow the instructions hereunder in order to avoid the error due to heat diffusion from sensor tip towards sensor top.

Type of application

